



Erratum:

**Erratum to: Bending behavior of double-row stabilizing piles with
 constructional time delay**

Yang YU¹, Yue-quan SHANG¹, Hong-yue SUN^{†2}

(¹College of Civil Engineering and Architecture, Zhejiang University, Hangzhou 310058, China)

(²Department of Ocean Science and Engineering, Zhejiang University, Hangzhou 310058, China)

[†]E-mail: shy@zju.edu.cn

doi:10.1631/jzus.A12e0027

Erratum to: J Zhejiang Univ-Sci A (Appl Phys & Eng) 2012 13(8):596-609

doi:10.1631/jzus.A1200027

The original version of this article unfortunately contained a mistake. In p.597, the minus on the right side of Eq. (1) “ $EI \frac{d^2 y_{cp}}{dz_{sl}^2} = -M_{sl}(z_{sl})$ ” was incorrect.

The correct version is given below:

$$EI \frac{d^2 y_{cp}}{dz_{sl}^2} = M_{sl}(z_{sl}).$$